

Oil Field Environmental Incident Summary

Incident: 20131223092038

Date/Time of Notice: 12/23/2013 08:58

Responsible Party: PHLLC

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SABROSKY 4-31-4C

Field Name: LITTLE KNIFE

Well File #: 6210

Date Incident: 12/23/2013

Time Incident: 05:30

Facility ID Number:

County: DUNN

Twp: 145

Rng: 97

Sec: 31

Qtr: SE SW

Location Description: JUST WEST OFF THE WELL PAD LOCATION ABOUT 30 IN THE LEASE ROAD DITCH.

Submitted By: DOUG HANSON

Received By:

Contact Person: DOUG HANSON
390 119TH AVE SW
KILLDEER, ND 58640

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1.3 Miles

Distance Nearest Water Well: 1.3 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7	barrels	0	barrels	7	barrels
Brine	2	barrels	0	barrels	2	barrels
Other	0	barrels	0	barrels	0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/20/2016

Clean Up Concluded: 12/26/2013

Risk Evaluation:

NONE

Areal Extent:

THE FLUID IS IN A NARROW BAND ALONG THE ROW 2 x 22.

Potential Environmental Impacts:

THERE WILL BE SOILS THAT ARE IMPACTED. THESE WILL BE REMOVED AND TAKEN TO

Action Taken or Planned:

THE WELL WAS SHUT IN AND THE PIPELINE ITSELF WAS ISOLATED. WE ARE CURRENTLY PICKING UP THE FLUIDS AND WILL BEGIN TO EXCAVATE THE LINE.

Wastes Disposal Location: FLUIDS FROM THIS RELEASE WILL BE RECYCLED, OIL WILL GO INTO THE PRODUCTION LINES, AND WATER WILL BE SENT ON TO DISPOSAL WELLS. ALL SOLIDS SOIL AND OTHER LIKE MATERIAL WILL BE TAKEN TO CHIMNEY BUTTE LANDFILL. CHIMNEY BUTTE WILL ALSO BE TASKED WITH HAULING SOLIDS.

Agencies Involved:

Updates

Date: 12/23/2013 **Status:** Reviewed - Follow-up Required

Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill was on a pipeline ROW; not contained according to NDDoH standards. Followup required.

Date: 12/30/2013 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

15:48, on location. Top layer of ground has been scraped up in ~40x80 ft area at location indicated in report. No visible stain within scraped area or in snow/vegetation beyond it.